

**RESPONSE TO ASH POND OBSERVATIONS AND RECOMMENDATIONS PER  
AECOM'S EAST ASH POND VISUAL SITE INSPECTION REPORT - 2020**

**Documented to meet 257.83(b)(5)**

	<b>DEFICIENCY/OBSERVATION (inspection recommendation #)</b>	<b>CORRECTIVE MEASURE</b>
1	Minor erosion ruts on the northeast outer embankment slope adjacent to the hopper.	Ruts graded flat along northeast outer embankment and re-established grassy vegetation.
2	Vegetation growth on multiple embankment slopes.	Vegetation knocked down at multiple locations.